

(Prior Art)






FIG. 2
(Prior Art)








		FIG. 9			FIG. 10
x32 x1 x2 x3 x4 x5 x6 x7 x8 x9 0 0	\oplus	$ k_1 k_2 k_3 k_4 k_5 k_6 k_9 k_{10} k_{11} k_{12} (k_7 \oplus k_5) (k_8 \oplus k_6) $ FIG. 9	x8 x9 x10 x11 x12 x13 x14 x15 x16 x17 0 0 0	\oplus	$ k_{13} k_{14} k_{15} k_{16} k_{17} k_{18} k_{21} k_{22} k_{23} k_{24} (k_{19}\oplus k_{17}) (k_{20}\oplus k_{18}) $ FIG. 10

		ĦĠ.	
0		$k_{25} \left k_{26} \left k_{27} \right k_{28} \left k_{29} \left k_{39} \left k_{34} \right k_{34} \left k_{35} \left k_{36} \left (k_{31} \oplus k_{29}) \left (k_{32} \oplus k_{30}) \right \right. \right. \right.$	
0		$(k_{31} \oplus k_{29})$	
X25		k36	
X24	\bigcirc	k35	
.x23	\oplus	k34	
X22		k ₃₃	
X21		k30	
x20		k29	
X19		k28	
x18		k27	
X ₁₆ X ₁₇ X ₁₈ X ₁₉ X ₂₀ X ₂₁ X ₂₂ X ₂₃ X ₂₄ X ₂₅		k26	
x16		k25	

